



50012 OAK TORSION DINING TABLE
ASSEMBLY INSTRUCTION FOR TABLE INSTALLATION

HARDWARES

			
JCBC SCREW M8x80 (3X)	JCBC SCREW M8x16 (9X)	METAL PLATE (SMALL) (1X)	METAL PLATE (LARGE) (1X)

TOOL




IN YOUR PACKAGE :

ASSEMBLY INSTRUCTION
HARDWARES (AS LISTED ABOVE)

PARTS TO BE INSTALLED


1. TABLE TOP 1 pc
2. CENTER LEG 1 pc
3. LEG BASE 1pc




SYMBOLS



DIRECTION




NUMBER OF
PERSONS NEEDED





USE L KEY
TO TIGHTEN

NOTICE





50012 OAK TORSION DINING TABLE
ASSEMBLY INSTRUCTION FOR TABLE INSTALLATION

A INSTALLING METAL PLATE TO THE CENTER LEG



! TIGHTEN FULLY



B INSTALLING CENTER LEG TO TOP TABLE



! TIGHTEN FULLY

50012 OAK TORSION DINING TABLE
ASSEMBLY INSTRUCTION FOR TABLE INSTALLATION

C INSTALLING LEG BASE



USE THE SCREW M8x80

D FINISH

