











BASEL-G






50 51 RM 06




#	ART. NR	L	W	T	Q	Col.No
1	1335	551	374	22	2	1
2	1334	547	336	22	3	1
3	1332	547	336	16	1	1
4	1333	547	336	16	1	1
5	1317	160	336	16	1	2
6	1318	160	336	16	1	2
7	1319	160	336	16	1	2
8	1320	160	336	16	1	2
9	1313	300	120	16	1	2
10	1314	300	120	16	1	2
11	1312	390	87	16	1	2
12	1253	1930	548	16	1	2
13	1324	426	188	16	1	2
14	1297	1930	60	16	2	2
15	1329	405	308	2,5	1	1



ø8
WALL DRILL



ø8x30mm A	ø6,4x50mm B	ø6,4x60mm B1	ø15/12mm C	D1	E	E1	ø3.0x16mm P1
22	23	4	14	14	10	27	5
4mm	ø5.0x13mm	ø3.5x16mm	ø8.0x50mm			4.0x27mm	
O	P9	P4	Z2	N	S1	P18	
1	4	1	1	1	1	2	
L-300 L	R PR1	U	ø3.0x20mm P7	ø4.0x25mm P12	F4		
1SET	4	2	4	4	4		







2/6

3

	B
4	
	E1
4	

4mm

O





4

	B
15	
	E1
15	



4mm

O



5

	E
8	





6

$\varnothing 6,4 \times 60 \text{ mm}$		$\varnothing 6,4 \times 50 \text{ mm}$
B1	E1	B
4	8	4


4 mm

O
1



7

$\varnothing 4,0 \times 25 \text{ mm}$	
P12	F4
4	4



8

ø8x30mm



A

2

ø15/12mm




C

2




D1

2




9




U

4







10




E

2






11




P1

5



2




S1

1








P18

2



13



14

